

Description of Event

On 2/3/2021 at 01:54 hrs a leak developed in the H5801B pass 2 outlet swing ell on the exterior side of the pipe. [REDACTED]

[REDACTED] The leak occurred with the line charged with oil and the emergency steam introduced. Significant amounts of oil and steam were emitted from the leak and covered the unit.

